


25~	C1	C2	C3	C4
50~				
60~	0.5	0.015	0.01	2.002

SUPREME
 SCHEMATIC WIRING DIAGRAM - MODEL 502
 GREENWOOD MFG. CO. U.S.A.

DATE: 6-15-57
 NO. 1606-C

001
0001
00004



F	C	A01	A01	A01
60~	C			
50~				
42~				
25~				

SUPREME
WARRANTY
GREENWOOD MISS. U.S.A.

SCHEMATIC WIRING
DIAGRAM MODEL 5025

DRAWN BY: *W.K. Gandy*
CHECKED: *W.K. Gandy*
DATE: 9-16-57
NO. 1688-C

A B C D E F 6 D.C.V. A.C.V. OHMS ELEC.

REV	BY	DATE

1400V
C₄
350V
C₅
140V
C₆
7V

ELECTROSTATIC
ELECTROLYTIC

20 MEG
2 MEG
OHMS COM.

MEG OHM
3000
OHM
610
110
20 M
2 M
200



SUPREME

Testing Instruments

"SUPREME BY COMPARISON"

Downloads Provided Free At
www.SuprmeInstruments.org

Not For Resale